

# **ÅAC Sirius Product Family Errata**

## **Rev. B**

## Introduction

### Purpose of document

This document details the errata in the AAC Sirius Breadboard and its manual, RD1

### Revision log

Rev	Date	Change description	Prepared
A	2016-10-07	First issue	E. Zachrisson
B	2016-11-03	Update for release 0.7.0	M. Werner

### Reference documents

Rev	Document Ref	Document name
RD1	204911, L	Sirius Breadboard Manual

## List of errata

Table 1 specifies which devices and what revisions that are affected by the errata described in this document.

Table 1 Affected units

Errata description	OBC-S Breadboard	TCM-S w. o. Software	TCM-S w. software
<b>System</b>			
#1061 Error detection and recovery unverified	All	All	All
<b>TCM-S Core Application</b>			
#1537 PUS packet size limitation			All
#1558 Spurious warning generated when entering AD mode			All
#1576 RMAP data checksums are not checked nor generated			All
#1589 TCM-S Accepts TCs with bad MAPID			AI
#1619 Download fails when sweeping packet sizes			All
#1714 Mass memory status is not retained between power cycles			All
#1752 Downloading and receiving spacewire simultaneously			All
#1788 Unable to set TM bitrate divisor to 0xFF			All
#1816 TC_BUFFER_CNT field is always 0 upon RMAP TCStatus readout			All
#1817 TC errors and TM error notification			All
#1818 TM timestamping not implemented			All
#1824 Unable to read CPDU index			All
#1839 No PUS success report is generated when sending TC to TCM-S			All
#1909 data frames can not be sent when idle frames are switched off			All
#1911 Mass memory, block 0 – 3 are reserved			All
#1944 Reading from spacewire fails when updating read/write pointers			All
#1629 Cannot handle spacewire packets of maximum size			All
<b>Spacewire</b>			
#1155 Minimum pkt size limitation	All	All	All
<b>GDB</b>			
#1207 writing and reading to non-32-bit-aligned addresses does not work	All	All	All

## System

### #1061 Error detection and recovery unverified

<b>Description</b>	Many of the error detection and recovery mechanisms are currently unverified outside of radiation testing due to the lack of mechanisms of injecting errors..
<b>Impact</b>	Possible non-working error detection and recovery algorithms, non-working error counting registers
<b>Suggested Workaround</b>	None

## TCM-S Core Application

### #1537 PUS packet size limitation

<b>Description</b>	The current mass memory implementation only support 32 bit aligned reads. When unaligned packets are stacked on top of each other, packets will start on unaligned offsets which are forbidden.
<b>Impact</b>	If unaligned reads are performed the application may potentially crash. Data will not be successfully retrieved
<b>Suggested Workaround</b>	All PUS packet sizes must be 32 bit aligned, possibly extending the packet up to 3 bytes to reach an 32 bit aligned size.

### #1558 Spurious warning generated when entering AD mode

<b>Description</b>	An invalid warning is generated when the TCM Core Application changes to AD mode.
<b>Impact</b>	None
<b>Suggested Workaround</b>	Disregard message on the debug UART.

### #1576 RMAP data checksums are not checked nor generated

<b>Description</b>	Due to performance reasons the incoming data CRC on RMAP commands is not checked nor is any CRC generated on outgoing RMAP commands.
<b>Impact</b>	Corrupt data packets may enter / leave the system
<b>Suggested Workaround</b>	Do not check data CRC on messages from the TCM Core Application.

### #1589 TCM-S Accepts TCs with bad MAPID

<b>Description</b>	The TCM-S accepts telecommands with MAPID=1 but should only accept command with MAPID=0
<b>Impact</b>	TCs with wrong MAPID are accepted and routed in the system
<b>Suggested Workaround</b>	None.

### #1619 Download fails when sweeping packet sizes

<b>Description</b>	When downloading packets of size 50k or larger from Mass Memory, the download fails and the TCM-S throws a bus-error
--------------------	--

## AAC Sirius Product Family Errata

	and crashes.
<b>Impact</b>	Downloading PUS packets of size 50 k or larger will not work.
<b>Suggested Workaround</b>	Don't use PUS packet larger than 20k.

### #1714 Mass memory status is not retained between power cycles

<b>Description</b>	Current driver implementation for mass memory use block 0 – 3 for tracking bad blocks.
<b>Impact</b>	Any data written to block 0 – 3 will be wiped out by the driver upon initialization
<b>Suggested Workaround</b>	Do not use block 0 - 3

### #1752 Downloading and receiving spacewire simultaneously

<b>Description</b>	When doing a download of a couple of megabytes and RMAP commands are received over spacewire causes issues such as problems with buffer allocation, wrong packet content in download.
<b>Impact</b>	Commands not handled, downloaded data not correct
<b>Suggested Workaround</b>	Don't send RMAP-commands while doing a download. Divide a larger download into several, smaller downloads instead.

### #1788 Unable to set TM bitrate divisor to 0xFF

<b>Description</b>	Setting different bitrates up to 0xFE by a RMAP command works, but setting a value of 0xFF has no effect
<b>Impact</b>	Setting a bitrate to 0xFF over RMAP is not working
<b>Suggested Workaround</b>	Don't use a TM divisor of 0xFF. If needed, do required configurations of the downlink of the Ground Station Equipment.

### #1816 TC\_BUFFER\_CNT field is always 0 upon RMAP TCStatus readout

<b>Description</b>	When performing the RMAP TCStatus command via RMAP the TC_BUFFER_CNT aka Length of the last received TC frame field is always zero.
<b>Impact</b>	The reported length of the last received TC is not valid
<b>Suggested Workaround</b>	None.

### #1817 TC errors and TM error notification

<b>Description</b>	Asynchronous error reporting of TC and TM errors are not implemented.
<b>Impact</b>	Notification messages when a TM or TC error occur will not be send over SpW.
<b>Suggested Workaround</b>	Use RMAP command TMStatus to get status of TM path. Use RMAP command TCStatus to get status of TC path.

### #1818 TM timestamping not implemented

<b>Description</b>	The TM timestamping and TMTSControl RMAP command is currently not implemented
<b>Impact</b>	TM timestamping does not work
<b>Suggested</b>	None

Workaround	
------------	--

### #1824 Unable to read CPDU index

Description	The CPDU index is cleared upon CPDU-interrupt, so the TCM-S application cannot read the last activated CPDU-index.
Impact	Not possible to get CPDU index by RMAP-command.
Suggested Workaround	None.

### #1839 No PUS success report is generated when sending TC to TCM-S

Description	When a TC with an APID addressed for the TCM-S application, no success report is generated.
Impact	When sending a TC to the TCM-S, no information if the command was received will be reported to the Ground Station
Suggested Workaround	None.

### #1909 data frames can not be sent when idle frames are switched off

Description	If generation of Idle-frames is disabled, no TM frames will be generated.
Impact	No data can be send on the downlink.
Suggested Workaround	Don't disable generation of Idle-frames.

### #1911 Mass memory, block 0 – 3 are reserved

Description	Current driver implementation uses block 0 – 3 for tracking bad blocks.
Impact	Any data written to block 0 – 3 will be wiped out by the driver upon initialization
Suggested Workaround	Do not use block 0 - 3

### #1944 Reading from spacewire fails when updating read/write pointers

Description	If a read from spacewire occurs soon after a read/write pointer update, received spacewire data may be corrupt
Impact	Pointer update commands cannot be used together with continuous spacewire traffic
Suggested Workaround	Wait 0.5s after triggering a pointer update before sending further spacewire traffic

### #1629 Cannot handle spacewire packets of maximum size

Description	Due to the TCM core app reading spacewire packets into a buffer of size SPWN_MAX_PACKET_SIZE at offset 128, a packet which is larger than SPWN_MAX_PACKET_SIZE - 128 will cause a buffer overflow.
Impact	Maximum spacewire packet size is less than specified
Suggested	Limit spacewire maximum packet size to

<b>Workaround</b>	SPWN_MAX_PACKET_SIZE - 128
-------------------	----------------------------

## Spacewire

### #1155 Minimum pkt size limitation

<b>Description</b>	Packets smaller than 4 bytes are not received correctly.
<b>Impact</b>	Packets small than 4 bytes cannot be used.
<b>Suggested Workaround</b>	All spacewire packets must have size between 4 and 65535 octets

## GDB

### #1207 writing and reading to non-32-bit-aligned addresses does not work

<b>Description</b>	The debugger interface to the OpenRISC CPU does not support byte writing and reading on non-32-bit-aligned addresses
<b>Impact</b>	When using gdb single bytes cannot be manipulated nor observed.
<b>Suggested Workaround</b>	Align all writes and read on a 32 bit data word basis, i.e. step the address by 4 and write 32 bits at a time.

## **ÅAC Microtec AB**

Uppsala Science Park,  
Dag Hammarskjölds väg 48,  
SE-751 83 Uppsala, Sweden.  
Phone: +46 18 56 01 30  
[www.aacmicrotec.com](http://www.aacmicrotec.com)  
[info@aacmicrotec.com](mailto:info@aacmicrotec.com)